






F / G. 1



$$F_1 > F_2$$

$$F_1 \approx F_2$$

$$F_1 < F_2$$



000090" 00000560

FIG. 3A




THE PRESSURIZED FLUID WAS NOT SUPPLIED

FIG. 3B



POLISHING PRESSURE 400gf/cm²
PRESSURE OF PRESSURIZED FLUID 200gf/cm²
THE PRESSURIZED FLUID IS SUPPLIED ONLY TO THE FIRST CHAMBER C₁

FIG. 3C



THE PRESSURIZED FLUID IS SUPPLIED ONLY TO THE THIRD CHAMBER C₃

000000" 8866560




FIG. 4C

FIG. 4B

FIG. 4A




[illegible]

FIG. 4D


F / G. 5



F 1 G. 6



00000000000000000000000000000000



• • • •